



## How to adjust a vertical door on a toolbox or service body that does not seal evenly from top to bottom

If the vertical door on a service body does not seal evenly from top to bottom it can be adjusted using a common 2x4 piece of wood.



Insert the 2x4 between the door and the frame in the corner that is NOT bowed out. Be sure to place the 2x4 away from the latching mechanism, so as not to damage it. You may choose to cushion the board with a cloth to protect the paint. Apply light pressure on the door on the end that is bowed out. It does not take much pressure to adjust the gap. Adjusting a door is sometimes easier with two people; one to hold the 2x4 and one to apply the pressure. Check the adjustment by closing the door to make sure it seals evenly.

For further assistance, contact technical support at RKI, Inc.