



### **How to adjust the knife edge on the door of a service body**

If the knife edge on a service body door does not seat in the center of the square bulb seal all the way around the door, either the seal is not properly installed, or the knife edge needs adjustment.

Place a crescent wrench on the knife edge where it needs adjusting. Apply light pressure in or out to move it to the center of the bulb seal.



For further assistance, contact technical support at RKI, Inc.